Summary of Decision of the Building Committee Building Committee II 2/2024 held on 25.3.2024

BCII 1 2/2024 (a)

Non-provision of fire barrier between existing staircases in a Issues (i) : historic building.

- All exit routes of some tiers/floors of theatre in a historic (ii) theatre building discharging to the same thoroughfare of inadequate width.
- (iii) Existing staircases' landings with inadequate length in a historic building.
- (iv) Existing staircase with inadequate width, substandard landing, risers and treads in a historic building.

(i), (iii) Decisions Having considered the circumstances of the case and the proposed compensatory and management measures, the & (iv)

committee had no objection to the deficiencies of existing

staircases.

(ii) Having considered the population of theatre, the proposed MOE arrangement and the previous approved uses of the building, the committee had no objection to all exit routes of some tiers/floors of the theatre discharging to the same thoroughfare of inadequate width.